

Oil Field Environmental Incident Summary

Incident: 20150917165628 **Date/Time of Notice:** 09/17/2015 16:56

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: HA-DAHL-152-95- 0706H-2

Field Name: HAWKEYE

Well File #: 20755

Date Incident: 9/17/2015

Time Incident: 08:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 95

Sec: 7

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1500 Feet

Distance Nearest Water Well: 1500 Feet

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	3	Gallons

Recovered	Units
-----------	-------

Followup	Units
3	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 10/7/2015

Risk Evaluation:

There is no immediate risk to report at this time. The fire was no longer burning when the Hess Lease Operator arrived on site.

Areal Extent:

Potential Environmental Impacts:

There was some damage to the offsite vegetation from the fire. There are no other potential environmental impacts to report at this time.

Action Taken or Planned:

The landowner will be notified by the Hess Land Department. Arrangements will be made to have the impacted material cleaned up.

Wastes Disposal Location: The recovered waste will be disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 9/18/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 9/29/2015 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 09:00, off site 09:24. Clear, 48 degrees, wind south at 10 mph. Light spray 75 yards into stubble field, followed by a small fire 20 yards into stubble. Oil/crude material was captured by the stubble. Crop 100 percent harvested.

Date: 9/1/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 9/1/2016, at 10:35 a.m. Walked the perimeter of pad. Vegetation growth is consistent with no areas of distress noticed at this time. No further follow-up required.

Date: 9/12/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

No Further Action letter dated September 12, 2016 was sent.

Date: 9/12/2016 **Status:** No Further Action Requested

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the analytical provided in the report and on-site observations, area appeared to have been remediated appropriately. No further follow-up needed, and No further Action letter drafted.

Date: 9/12/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Another NDDoH inspector forwarded me an email and attached closure letter from the environmental consultant. The closure letter showed that post-excavation soil samples collected from the location did not exceed NDDoH guidance levels. Report added to incident folder. No further follow-up needed.